



COVERALL P540

EUROPEAN STANDARDS

EN 342:2004

Protective clothing – Ensembles and garments for protection against the cold (< - 5° C)

EN ISO 340

Protective clothing – General Requirements

EU Type-examination (Module B)

n° 0072/282/162/04/14/0026/EX01 04 14

PPE TECHNICAL FEATURES

- Fur collar
- Front zipper with protective flap and press studs
- One chest pocket with protective flap and press stud
- Two lower pockets with thermal insulation and protective flaps
- Knitted cuffs for perfect fit
- Adjustable waist with velcro straps on the back
- Leg zipper 57 cm long on the side with protective flap and press studs
- Coverall easy and fast to put on
- Thermal insulation and quilted lining
- Temperature is maintained in humid environments
- Resistant, breathable, easy maintenance

PACKAGING

Cardboard box

ALLERGIES

Anti-allergic finish, designed for human use

STORAGE INSTRUCTIONS

Store in a dry place. Protect against high temperatures and UV rays exposure. Once removed from the original packaging, it can be stored on a hanger.

TECHNICAL FILE

PERFORMANCE LEVELS

Tear resistance outer fabric

Evaporative Resistance R_{ET}

Air permeability (ISO 9237)

Resistance to water penetration

Thermal insulation I_{cler}

Comply

36 m² PA/W

Class 2

X

0,493 m² K/W (B)

Thermal insulation	Light activity Exposure	Light activity Exposure	Medium activity Exposure	Medium activity Exposure
I_{cler} m² K/W	8 hours ° C	1 hour ° C	8 hours ° C	1 hour ° C
0,493	- 17,5° C	- 38° C	- 42,4° C	- 62,1° C

PPE COMPOSITION

- Synthetic Fur 100% acrylic fibre 700 gr/m²
- Outer fabric 100% polyamide 6.6 185 gr/m²
- Lining 100% polyester 62 gr/m²
- Thermal insulation 100% polyester 220 gr/m²
- Knit 100% acrylic fibre

Colours

Navy, black, royal, green, green bring, red, orange, white, grey, chino, caramel, brown

Sizes

XXS – XXXL

USE INSTRUCTIONS

Keep PPE closed when in use. Do not remove the conservation label. Respect the cleaning instructions on the label attached to the PPE. Not following washing instructions can significantly shorten the life of the PPE. PPE must be kept in a good state of cleanliness and conservation. PPE is water permeable.

WASHING INSTRUCTIONS

Maximum washing temperature 40° C (normal process). Bleaching is not allowed. Do not tumble dry. Do not iron. Do not dry clean.

