



TROUSERS P126

EUROPEAN STANDARDS

EN 342:2004 CAT II

Protective clothing – Ensembles and garments for protection against the cold (< - 5° C)

EN 340

Protective clothing – General Requirements

EU Type-examination (Module B)

n° 0072/282/162/06/97/0162

PPE TECHNICAL FEATURES

- High rise back for kidney protection
- Elastic waistband for a perfect fit and to prevent cold airlifts
- Front zipper with press stud
- Elastic knit adapted to the ankles for a perfect fit
- Elastic foot to keep the trousers in place
- Thermal insulation and quilted lining
- Temperature is maintained in wet environments
- Resistant, breathable, easy maintenance

PACKAGING

Cardboard box

ALLERGIES

Anti-allergic finish, designed for human use

STORAGE INSTRUCTIONS

Store in a dry place. Protect against high temperatures and UV rays exposure. Once removed from its original packaging, it can be stored on a hanger.

USE INSTRUCTIONS

Keep the PPE closed when in use. Do not remove the conservation label. Respect the cleaning instructions on the label attached to the PPE. Not following washing instructions can significantly shorten the life of the PPE. The PPE must be kept in a good state of cleanliness and conservation. The PPE is water permeable.

TECHNICAL FILE

PERFORMANCE LEVELS

Outer fabric tear resistance	X
Evaporative Resistance R_{ET}	Level 3
Air permeability (ISO 9237)	Class 2
Resistance to water penetration	X
Thermal insulation I_{cler}	0,270 m² K/W (B)

Thermal insulation	Light activity Exposure	Light activity Exposure	Medium activity Exposure	Medium activity Exposure
I_{cler} m² K/W	8 hours ° C	1 hour ° C	8 hours ° C	1 hour ° C
0,270	- 5° C	- 18° C	- 12° C	- 24° C

PPE COMPOSITION

- Outer fabric 100% nylon 62 gr/m²
- Lining 100% polyester 62 gr/m²
- Thermal insulation 100% polyester 140 gr/m²
- Knit 100% acrylic fibre

Colours Navy, white

Sizes XXS – XXXL

WASHING INSTRUCTIONS

Maximum washing temperature 40° C (normal process). Bleaching is not allowed. Do not tumble dry. Do not iron. Do not dry clean.

