



SET P2925

EN 342:2017

Protective clothing – Ensembles and garments for protection against the cold (< - 5°C)

EN ISO 13688:2013

Protective clothing – General Requirements

EU Certificate of Conformity nº 001/2022

PPE DESCRIPTION

- Thermal insulation and quilted lining
- Temperature is maintained in wet environments
- Resistant, breathable, easy maintenance

JACKET P392

- Fur collar
- Front zipper with protective flap and press studs
- 1 chest pocket with protective flap and an opening for pens
- 2 lower pockets with thermal insulation and protective flaps
- Inner elastic on the back to avoid the cold
- Knitted cuffs for a perfect fit

TROUSERS P295

- High rise back for kidney thermal protection
- Front zipper with protective flap and press studs
- Adjustable suspenders
- Leg zippers 57 cm long with protective flaps and press studs
- 1 back pocket
- 2 front pockets with thermal insulation

PACKAGING

Cardboard box

ALLERGIES

Anti-allergic finish, designed for human use

STORAGE INSTRUCTIONS

Store in a dry place. Protect against high temperatures and UV rays exposure. Once removed from the original packaging, it can be stored on a hanger.

TECHNICAL FILE

PERFORMANCE LEVELS

(Tested on model size L)

Air Permeability

Thermal Insulation

Class 2 AP 58,1 mm / s

I_{cler} 0,351 m² K/W (B)

Thermal Insulation	Light activity Exposure	Light activity Exposure	Moderate activity Exposure	Moderate Activity Exposure
I_{cler} m ² / KM	8 hours ° C	1 hour ° C	8 hours ° C	1 hour ° C
0,351	- 6° C	- 23° C	- 24° C	- 42° C

PPE COMPOSITION

- Fur 100% acrylic fibre 700 gr/m²
- Knitting 100% acrylic fibre
- Outer fabric 100% polyamide 6.6 185 gr/m²
- Lining 100% polyester 62 gr/m²
- Thermal Insulation 100% polyester 220 gr/m²

Colours

Navy, black, green, white, royal, bring green, red, orange, grey, chino, caramel, brown

Sizes

XXS – XXXL

USE INSTRUCTIONS

Keep the PPE closed when in use. Do not remove the conservation label must. Respect the label cleaning instructions. If not, it can shorten the life span of the PPE. The PPE must be kept in a good state of cleanliness and conservation. It is not permeable to water.

WASHING INSTRUCTIONS

Maximum washing temperature 40°C (normal cycle). Bleaching is not allowed. Do not machine dry. Do not iron. Do not dry clean.

